

INSTALLATION INSTRUCTIONS

Part# T16494A

TRANSMISSION PAN REPAIR NUT

For FORD 5R55S & 5R55W

1. If the bolt and the inner cap are in good shape. Remove them and grind the flange off of the nut down to the large diameter attached to the pan.
2. Reinstall the bolt through the existing nut. Then thread the pan nut repair onto the bolt. Be careful not to tear the small O-ring in the top of the nut, a small amount of transmission fluid on the O-ring will help the O-ring go over the bolt.
3. Thread down until the nut tightens against the pan. This seals around the old nut so it will not leak.
4. Reinstall the pan and fill as usual.

Teckpak Hotline: 1-800-527-2544
www.teckpak-fitzall.com