

T45207E

MADE IN THE U.S.A.



FITZall

EXHAUST CLAMP HARDWARE

Fits all 6L80 Trucks with 4.3, 4.8,
5.3 and 6.0 engines 2009 - 2021




Reuse
OEM 20779889 strap,
which is not included.




7 57738 42013 5

INSTRUCTIONS



1. To repair the worn hardware, simply cut the existing clamp in the middle until the bolts fall off.



2. Align the two flats to the bolt and attach the new hardware on each side with the appropriate wrench or tool.